

Oil Field Environmental Incident Summary

Incident: 20151124193325 **Date/Time of Notice:** 11/24/2015 19:33

Responsible Party: HUNT OIL COMPANY

Well Operator: HUNT OIL COMPANY

Well Name: SIOUX TRAIL 160-101-35-26H-1

Field Name: SIOUX TRAIL

Well File #: 29269

Date Incident: 11/24/2015 **Time Incident:** 10:30

Facility ID Number:

County: DIVIDE

Twp: 160

Rng: 101

Sec: 35

Qtr:

Location Description:

Submitted By: Alan Clark

Received By:

Contact Person: Brian Gilmour
1900 NORTH AKARD STREET
DALLAS, TX 75201-2300

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: Yes

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	200	Barrels	200	Barrels	200	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 12/7/2015

Clean Up Concluded: 12/3/2015

Risk Evaluation:

The spill was contained on well site. A spill response crew was on location by noon and sucking up salt water. Risk would be minimal.

Areal Extent:

Potential Environmental Impacts:

After salt water clean up is complete, clean dirt will be put back on location. No environmental impacts.

Action Taken or Planned:

There will be a meeting with pumpers to remind them of the severity of careless actions.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 11/25/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.